

# SURVEY RECOVERY FORM

City of Everett  
Department of Public Works

State of Washington  
County: Snohomish

Station Name: 703 58 01

Horizontal Datum: NAD83/91

Vertical Datum: NAVD88

Established By: DOT-Linn & Asso

Control Point ID: Book: 703

Page: 58

Pt#: 01

Date: 9/10/99

Section: 08

Township: 28 N

Range: 5 E

LATTITUDE: (5 decimal places) 47 56 00.37099

LONGITUDE: (5 decimal places) 122 11 39.71929

ORTHOMETRIC HEIGHT: \_\_\_\_\_ Feet  
\_\_\_\_\_ Meters

## Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	343439.021	1306796.878	0.999947415	-01 00 47.9
Meters	104680.423	398312.485		

### HORIZONTAL DATA:

Horizontal position established by:

\_\_\_\_\_ resection survey, comments

☒ GPS survey, GPS adjustment software used: Trimble RTK, Trimbal Software

\_\_\_\_\_ other, explain: \_\_\_\_\_

surveyor's estimated relative positional accuracy: 0.4 ft n @ 0.4 ft E 95% confidence Level Constrained to DOT points GP31005-81, through GP31005-88

surveyor's estimated absolute positional accuracy: ft @ 1 sigma \_\_\_\_\_ @ \_\_\_\_\_ % confidence Level

### VERTICAL DATA:

Vertical position established by: WJA

\_\_\_\_\_ differential leveling to: \_\_\_\_\_ order accuracy

\_\_\_\_\_ GPS survey, accuracy within \_\_\_\_\_ ft \_\_\_\_\_ meters

surveyor's estimated relative positional accuracy: \_\_\_\_\_ ft @ \_\_\_\_\_ 95% confidence Level

surveyor's estimated absolute positional accuracy: \_\_\_\_\_ ft @ \_\_\_\_\_ 95% confidence

### MONUMENT DESCRIPTION

A 1-3/4 inch brass plug without a punch mark set in the top of a concrete monument. 4 PK nails were found in the asphalt about 2 feet in each direction. The point positioned was the intersection of these lines.

### TO REACH

Located at the center of intersection of Juniper Drive and Yew Street.

### REFERENCES

Az from North	Distance	Reference Description
---------------	----------	-----------------------

Month & Year Recovered:

Condition of Mark:

Recovered By: